D.I.IZ 3D3 II Dally Visible Ellission

### VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: 1st Shift 2nd Shift Time: or 5 pm Unit Visual Comments Inspection NORMAL or ABNORMAL Visible Emission From Shaker Nor Visible Emission From Discharge Conveyor System

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

D.1.12 SDS II Daily Visible Emission Notations reconstruction

VISIBLE EMISSION NOTATIONS				
Inspector:	Noland			
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shift	t Time:			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Norm			
Visible Emission From Discharge Conveyor System	Norm			

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE ENVISCION NOTATIONS

U.1.12 SUS II Dally Visible Emissio Notations . . . . .

VISIBLE EMISSION NOTATIONS			7		
Inspector: Laime N Cocinci					
Date of Inspection: 6/02/15					
Shift: 1st Shift or 2nd Shift	Time:	5 An			
Unit Control of the C	Visual Inspection <u>NORMAL</u> or ABNORMAL			omments	
Visible Emission From Shaker	NOR				
Visible Emission From Discharge Conveyor System	NOR				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: River Holi	ind			
Date of Inspection: 6/2/15				
Shift: 1st Shift or 2nd Shift	Time:	Siwin		
Unit	Visuali U inspection		omments	
	<u>NORMIAL</u> Of			i,
	<u>ABNÖRMAL</u>			
Visible Emission From Shaker	Normal			
Visible Emission From Discharge	1 3- (0000)			
Conveyor System	MONNEL			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspect	tor:	Jime /	V Cocie	10	
Date of	f Inspection:	6/3/1	7		
Shift:	1st Shift	6r 2.17g	Shift	Time:	5Am

		- 4	1	
that Unit	Visual		Comments	4-8
and Politics of the property o	Inspection		production of the state of the	(20,20) , $(20,20)$ , $(20,20)$ , $(20,20)$ , and $(20,20)$ , and $(20,20)$
	NORMAL			And the second s
	or .	The state of the s		
	<u>ABNORMAL</u>			
Visible Emission From Shaker	Nor			
Visible Emission From Discharge				
Conveyor System	NOR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Conveyor System

Inspect	or:	Sel	remy Hardin			
Date of	Inspection:	( -	4-15			
Shift:	1st Shift	or	2nd-Shift	Time:	5:00 an	

		<b>G V</b> . <b>V</b>			
Unit	Visual		Com	nments	
	Inspection				
	<u>NORMAL</u>				
	or <u>ABNORMAL</u>		Septiminary of the septiminary o		
Visible Emission From Shaker					
	Normal				
Visible Emission From Discharge					
Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

D.1.12 3D3 II Daily Visible Ellissio

**VISIBLE EMISSION NOTATIONS** Inspector: Date of Inspection: 1st Shift Shift: 6:00pm Unit Visual Comments Inspection NORMAL or **ABNORMAL** Visible Emission From Shaker Visible Emission From Discharge Conveyor System

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Visible Emission From Discharge

Conveyor System

AIDIDEE FIAIDDION MOLVILOND			•		
Inspector: Jeremy Hardin					
Date of Inspection:					
Shift: 1st Shift or Zand Shift	Time:	5:30 am			
Unit	Visual		Commen	nts	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
and the state of t	Inspection				Supplies of the Control
	<u>NORMAL</u>				
The state of the s					
	<u>ABNORMAL</u>				
Visible Emission From Shaker	Normal				

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

No coma!

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	Dar	ren B Gd	70 C		
Date of Inspection:		6-5-2013	~***	•	
Shift: 1st/Shift or	2nd Shift	Time:	6:00p.m		
Unit		Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Sh	aker	Nor			
Visible Emission From Di Conveyor System	scharge	Nac			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector: Damian 5a	elinas Jr		
Date of Inspection: 6-6-(	<i>'</i> 5		
Shift: 1st Shift or 2nd Shift	Time:	SAM	
Unit	Visual Vispection		Comments
	NORMAL.		
	OJ ABNORIMAL	The state of the s	
Visible Emission From Shaker	Nor	quantum	
Visible Emission From Discharge		GTRBS	
Conveyor System	Nor		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: R) ber M	olan 2				
Date of Inspection: 6 16/	2015			•	
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm			
Unit	Visual Inspection <u>NORMAL</u> Or		omiments		
Visible Emission From Shaker	ABNORMAL A				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

TIBIBLE ENTIREDICTOR TO	71770110			
Inspector: Ruber	5 Nober	DC 111		
Date of Inspection:	-1616			
Shift: 1st Shift or	2nd Shift	Time:	5:00pm	
(Unit		Misuzi ispeculain		Comments ,

Visible Emission From Shaker

Visible Emission From Discharge Conveyor System Som

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

TITE 202 II Dally Alsiple cillissious Morariana

VISIBLE EIVIISSION NOTATIONS					
Inspector: Laime 16	ORTA				
Date of Inspection: 6/8/15					
Shift: 1st Shift or 2nd Shift	Time:	5 AM			
Unit	Visual linspection NORMAL		Com	Imenis	
PART TO THE STATE OF THE STATE	ABNORMÁL				
Visible Emission From Shaker	NOR				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector: Part	1 B and The	
Date of Inspection:	618/15	
Shift: 1st Shift or	2nd Shift	Time: 6:45 0.00

		6.7000			
unit unit	Visual		Comme	ents	
	Inspection NORMAL				
	OII OII	erican and a second	All the second of the second o		
	ABNORMAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	Mac	economiscon .			
Conveyor System	1401				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NO	IAHONS			Paratorn I		
Inspector:	ereny H	ardin				
Date of Inspection: 6-	9-5					
Shift: 1st Shift or	2nd Shift	Time:	6:00an			
Limit		Visual Inspection INSPECTION INSPECTION OF ABNORMAL			Comments	
Visible Emission From Sh	aker	Normal				
Visible Emission From Di Conveyor System	ischarge	Normal	Control of the Contro			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

D.1.12 SDS II Daily Visible Emissions Notations . ...

AIZIBLE EMIZZION	INOTATIONS				
Inspector:	cremy Hardin				
Date of Inspection:	6-10-15				
Shift: 1st Shift	or 2nd Shift	Time:	5:00am		
grande Unit. Verge		Visual r Inspection <u>NORMAL</u> or ABNORMAL		omments described	
Visible Emission Fro	m Shaker	Normal			
Visible Emission Fro Conveyor System	m Discharge	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

D.T.TZ 2D2 II DSIIA AIRIBIG EMISSIOUS MOJario...

VISIBLE EMISSION NOTATIONS					
Inspector: Reben	Holad				
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	t Time:	500ph			
Unit 11	Visual Linspection <u>Normal</u> 22 For ABNORMAL		Com	oments	
Visible Emission From Shaker	Norm				
Visible Emission From Discharge Conveyor System	Norm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Ry Wen	Holad				
Date of Inspection:	/				•
Shift: 1st Shift or 2nd Shift	Time:	5, w m			
u Unit	Visuali Inspection		Co	mments	S. erpain (1) and object
	<u>NORMAL</u>			1750 a 1762 a 1764	
	oi <u>Abnormal</u>			<b>36</b> 4	
Visible Emission From Shaker	Normal				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			_		
Inspector: RIDER	Holad				
Date of Inspection:	1205				
Shift: (1st Shift) or 2nd Shift	t Time:	5:00pm			
⊎nit	Visual Inspection		Con Control of the Control of the Co	niments	
	<u>NORMAL</u>				
	ABNORMAL				
Visible Emission From Shaker	Normal				
Visible Emission From Discharge					
Conveyor System	11/20(max 1				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBL	E EMISSIC	N NC	TATIONS			_				
Inspect	or:	Ja	ine 110	CARCIA						
Date of	Inspection:	6,	13/15							
Shift:	1st Shift	or	2nd Shift	Time	JAM					
	Un	ir.		Visual Inspection NORIMAL			Comme	enies		

ABNORMAL

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

VISIBLE EMISSION NOTATIONS			<b></b> .		
Inspector:	en 3 luli	z			
Date of Inspection:	13/2015				
Shift: 1st Shift or 2nd Shift	Time:	5:20	-		
llinit	Visual Jinspecticin "s Normal	The plant of the control of the cont	Confidence of the second secon	ilonents profile the	
TAMES TO SERVICE AND SERVICE A	or ABNORMAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor	, and the same of			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual marner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS						
Inspector: Jamian Sa	linas Dr					
Date of Inspection: 6-14~	15				·	
Shift: 1st Shift or 2nd Shift	t Time:	SAM				
Unit	Visuali Inspection			Comments		
	" <u>NORMAL</u>					
	or ABNORMAL				12	i i
Visible Emission From Shaker	Nov	Section of the sectio	recent for the control of the contro			0.000
Visible Emission From Discharge	a )	_				
Conveyor System	Not					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: Darra	B adjoc			
Date of Inspection:	2015			
Shift: 1st Shift or 2nd Shift	Time:	6:00	].	
196girt :	Villegiaja Regjarentear <u>1940 mentek</u> 28		(Coinglaireigh)	
Visible Emission From Shaker	ABAIÓIRIKIAN A			
Visible Emission From Discharge		i ya Marika iliya ili alimi tuo wali ali alima kuniya iliya pananina da da alima iya da alimaka ada da alima i		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)


Conveyor System

AIZIBLE EMIZZION NOTATI	ONS			
Inspector:	Hardin			
Date of Inspection: 6/15/1	5			
Shift: 1st Shift or 2n	d Shift Time:	6:00am		
<u>Vinjî</u>	Váleyet Mása secúlcia <u>Mása secúlcia</u> Su Alsandanávan		Conginicair.	
Visible Emission From Shaker				
Visible Emission From Discha Conveyor System				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector:	Molane			
Date of Inspection:	2015			•
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm		
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		inments	
Visible Emission From Shaker	Mormal			
Visible Emission From Discharge Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



VISIBLE EMISSION NOTATIONS					
Inspector: Parl					
Date of Inspection:					
Shift: 1st Shift or 2nd Shif	Time: <	5,00 pm			
Unit	Misuai Iinspeatioin I <u>NORMAU</u> Of <u>ABNORIMAL</u>		. Con	nunenus	
Visible Emission From Shaker	000				
Visible Emission From Discharge Conveyor System	rod				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIDE	E EMISSION NOTATIONS						
Inspecto	or: Jaime N Go	MCia					
Date of	Inspection: 6/16/15					•	
Shift:	1st Shift or 2nd Shift	Time:	5 AM				
	Unit	Visual Inspection NORMAL E or ABNORMAL			Comments		
Visible	Emission From Shaker	NOR	Augustus Million and Control of C	re men en e	omen er er en skulletjere en de er	and an experimental property of a property of the first post of the second seco	The court is the court of the c
ł	Emission From Discharge or System	Nor	Come of the Company o				,

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NO	TATIONS		_	
Inspector:	Severy Hardin			
Date of Inspection:	17/15			
Shift: 1st Shift or	2nd Shift	ime: 6:00 pm	]	
Ungit	Vileuizh Iliner e-c'helin <u>E-c'helin iliner e-c'helin</u> eu A-Sint-Grenvean		Cratinjaniemes:	
Visible Emission From Sh	naker			
Visible Emission From Di Conveyor System	scharge Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Jamian	Salinas D	eringay ya ya madiga galamii Miliya ya katalii da katalii da katalii aya katalii aya katalii ya miina asay a ma			
Date of Inspection: 6-19-15					
Shift: 1st Shift or 2nd Shift	Time:	5. supm			
(diggit)	Vikeel Inggeedien Elogipal ei Alanogyval			indations.	
Visible Emission From Shaker	Nov		ferfix the control of function as the first and an extraction of		inde vedel finisse sinne Leathligh I. Roman og framskin tre godder i efficielle i de godder
Visible Emission From Discharge Conveyor System	Nor	h-1			

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up to shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

### VISIBLE EMISSION NOTATIONS

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

Inspect	ior: Dami	an Sal	1995 Br			
Date of	Inspection:	6-18-15	garantee o Paris Ade Milyanda Milyan ya mareey ya ah da Maraa 22 yeey ga ah mareey a			
Shift:	1st Shift or	2nd Shift	Time:	5,00pm		
	Hitaric		Vikiejali Niigi istalialia Niigi istalialia Si		Countients	

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

Nor

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EIVIISSION NOTATIONS				
Inspector: Jaime N. Garci	'G			
Date of Inspection: 6/20/15				
Shift: 1st Shift or 2nd Shift	t Time:	5 Am		
. Unit	Visual Inspection NORMAL Of		omments	
Willia Emission From Shaker	ABNORMAL			
Visible Emission From Shaker	Non	Control of the Contro		
Visible Emission From Discharge Conveyor System	Non	- Andrews		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



VISIBLE EMISSION NOTATIONS					
Inspector: Jaime N Garcie	- 9				
Date of Inspection: 6/01/15				•	
Shift: 1st Shift or 2nd Shift	Time:	5Am			
Unit	Visual Inspection		comments		
	<u>NORMAL</u> OJ <u>ABNORMAL</u>				
	<u>ABNORMAL</u>			Section 1	
Visible Emission From Shaker	Kor	· ·			
Visible Emission From Discharge					
Conveyor System	Nor	and a			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTA	IONS		
Inspector: Sereny	Hardin		
Date of Inspection:	(15		
Shift: (1st-Shift or 2	nd Shift Time:	600pm	
Utaiji}	Visual Ingarec'hein <u>intrekvale</u> ea <u>Alanio) inveal</u>		(Centiful areases
Visible Emission From Shak	er		
Visible Emission From Disch Conveyor System	arge		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

# VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: C 24-2015 Shift: 1st Shift or 2nd Shift Time: Visual: Inspection: Visual: Inspection: NOTATIONS Visual: Inspection: NOTATIONS Visual: Inspection: NOTATIONS Visual: Visual: Visual: Visual: NOTATIONS Visual: Visual: Visual: Visual: NOTATIONS Visual: Vis

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mar ner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

**Conveyor System** 

AISIBLE EMISSION NO LATIONS			_		
Inspector: Seceny Hav	din_				
Date of Inspection: 6/73/15					
Shift: 1st Shift or 2nd Shift	t Time:	7:00 pm			
Digita :	Miguel Migueciùcio Alorimale ea Albrioriman		Conduc	ides	
Visible Emission From Shaker	wormal				
Visible Emission From Discharge					
Conveyor System	vormal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Smello					
Date of Inspection: 6-24,15					
Shift: 1st Shift or 2nd Shift	Time:	SAM			
(dégife	Vilogel Inspection <u>Plocival</u> el Albriotheral		CG	untarcents:	
Visible Emission From Shaker	nor				
Visible Emission From Discharge Conveyor System	nov	·			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal missions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE EMISSION NOTATIO	NS				
Inspector: Sublen	Moland				
Date of Inspection:	4-15				
Shift: 1st Shift or 2nd	Shift Time:	57000 mm			
blair	Virsurat Eliospe colie in Eliosperole Eliosperole Albriotriviai		Control of the contro	dinisinis:	
Visible Emission From Shaker	Dom				
Visible Emission From Discharg Conveyor System	ge Norma				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE FIMISSION NO	IAHONS				
Inspector:	i Al Co	RUG			
Date of Inspection:	25/15				
Shift: 1st Shift or	2nd Shift	Time:	5 AM		
junje Ji	t design of	Micuri Nogredijen <u>Mortavije</u> 94		loinhniemys	
Visible Emission From SI	aker	XABNÖRIMAL NOR	*		
Visible Emission From D Conveyor System	ischarge	NOR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

#### VISIBLE EMISSION NOTATIONS

Inspector: Paul Lank	$\mathcal{C}$	37		
Date of Inspection: 6 - 25-	15			
Shift: 1st Shift or 2nd Shift	ft Time:	5:00 pr-		
Majir	Misuel Inspection <u>Morivial</u> or ABNORMAL		(Cotinhinicanass	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)


VISIBL	<u>E EMISSIO</u>	<u>N NO</u>	TATIONS			
Inspect	or:	Lim	N Garcia			
Date of	Inspection:	6/0	4/15			
Shift:	1st Shift	or	2nd Shift	Time:	5Am	:

Unite	Vicesi Vicesi	Comparis.	n <b>i :</b>	
	NORMAL er			
Visible Emission From Shaker	ABNIORMAI NOR			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			_	
Inspector: Ruban M	lend III			
Date of Inspection:	c-800			•
Shift: 1st Shift or 2nd Shift	: Time:	b.copm		
Ulgiri Tarahan Maria Maria	Visual Inspecticia AVISIMAL ea ABMORIMAL		Goinla D	
Visible Emission From Shaker	Norm			
Visible Emission From Discharge Conveyor System	Nom			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual marner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: Seremy 1	ardin			
Date of Inspection:	5			
Shift: 2st Shift or 2nd Shift	Time:	6;300m		
Unite	Viloyel Inige-edicin <u>idoeliya'ala</u> el		injunienas	
Visible Emission From Shaker	NOVMA)			
Visible Emission From Discharge Conveyor System	normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

### VISIBLE EMISSION NOTATIONS

Inspector:	Dos	ren R adra	e		
Date of Inspection:		6-28-20			
Shift: 1st Shift or	2nd Shift	Time:	7:00a.m		
i Diguit		Visural Interections I <u>NTOE (VISU</u> ISI ABINTOR (VISA)		indinite gits	
Visible Emission From Sh	naker	Nor			
Visible Emission From Di Conveyor System	scharge	Nor			·

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIDEE FIATISSION NOTATIONS	/				
Inspector: Hamlan S	alinas Jy				
Date of Inspection: 6-28-	15				•
Shift: (1st Shift) or 2nd Shift	t Time:	Spr			
Unit	Visuali Inspection (1888)		Comi	ments	
	<u>NORMAL</u>				
(d)	OF ABNORMAL				
Visible Emission From Shaker	Nov				
Visible Emission From Discharge	,				
Conve <b>y</b> or System	Not				

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIDIE ENVICCIONI NOTATIONIC

VISIBLE EMISSION NOTATIONS	<u>a</u>			
Inspector:	aljee			
Date of Inspection:	2015			
Shift: 1st Shift or 2nd Shift	Time:	7:00Am		
Uhait	Visuri Visuri		(Cólimiantealits	
	BYORIMAL			
	AEMORIMAL el			
Visible Emission From Shaker	M			
Visible Emission From Discharge Conveyor System	Nov			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



VISIBLE EMISSION NOTATIONS		_		
Inspector: Jachan M	dandli			
Date of Inspection:	15			•
Shift: 1st Shift or 2nd Shift	Time:			
Unit Visible Emission From Shaker	Maval Ilinsp edion Normal  ABNORMAL	Co	inimerius	
Visible Emission From Discharge Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



AIRIDEE EIMIRRION NOTATIONS		MINANTA 10 - 1 - 0 - 10 - 10 - 10 - 10 - 10 -	<u>.</u> .		
Inspector: Ruhin M	bland				
Date of Inspection: 63015					•
Shift: 1st Shift or 2nd Shift	Time:	5:00pm			
Winit:	Mayal Iinspection INORIMAL OI ABNORIMAL		Co	iniments	
Visible Emission From Shaker	Normal				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS	)		_		
Inspector: Jaime N G					
Date of Inspection:	15				
nift: 1st Shift or 2nd Shift T		5AM	]		
Unit	Misural Inispecifican I <u>nfortham</u> ol Abatorima			eluniagregaps.	
Visible Emission From Shaker	Nor	- Quality constructions			
Visible Emission From Discharge Conveyor System	Nor	4-atomorphics			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)